

Connected objects management

Create phasing

- [Introduction](#)
- [Drawings management](#)
- [GIS management](#)
- [Areas and axes management](#)
- [Print areas management](#)
- [Tasks management](#)
- **[Connected objects management](#)**
- [The Gantt chart](#)


Adding a polyline

In the Create phasing interface, go to the “Connected Objects” tab and click on the button .

Draw your polyline (here the traffic lane in superposition of the southern roadway), point by point with the left click. Once the last point has been positioned, exit the plot mode with a right-click.



In the options that appear on the right click, you can specify which arrow to display in the case of a one-way traffic lane



For more readability, it is possible to change the style of the polyline: just hover over it and right-click on one

of its segments, then choose **Settings** . Here we will change its color:

Edit:

One color #669966

Thickness 5.0

OK Cancel

Renaming a connected object

To rename the connected objects, they must be localized on the map.

To do this, go to the “Connected objects on selected drawing” tab, of the bottom menu of the Create phasing window, and use the visibility checkmarks to locate your connected object. Highlight the corresponding line and click on the “Edit” button.

Here we rename the polyline located at the top to “**Traffic North lane Phase 5**”:

Cursor coordinates[lon : -17.116536339045]

Gantt chart Tasks **Connected objects**

Name	Visible
Polyligne - 11921065	<input type="checkbox"/>
Polyligne - 11921069	<input checked="" type="checkbox"/>

Edit object name

Name Traffic North lane Phase 5

OK Cancel

Edit